



COORDINATE ROOF PENETRATIONS AND REPAIR WITH NEW WORK BELOW
REPAIRS TO ROOF SHALL BE WITH SAME MFG ROOFING MATERIALS AND TO
KEEP ROOF WARRANTY IN FORCE.

<div>ADDENDUM - 1</div> <div>Revisions</div>	<div>08-20-08</div> <div>Date</div>	<div>Approved: Medical Center Director</div>	<div>Seals</div>	<div>TAGGART FOSTER-CURRENCE GRAY ARCHITECTS, INC.</div> <div>4500 Burrow Drive North Little Rock, AR 72116 Phone: 501-758-7443 Fax: 501-753-7309 www.taggarch.com</div>	<div>Drawing Title</div> <div>ROOF PLAN - PLUMBING AND MEDICAL GAS</div>	<div>Project Title</div> <div>JLM MEMORIAL VETERAN'S HOSPITAL - EXPAND MICU</div>	<div>Date</div> <div>NOV 2013</div>	<div>Office of Facilities</div> <div>DEPARTMENT OF VETERANS AFFAIRS</div>	
		<div>Approved: Associate Director</div>			<div>Building Number</div> <div>1-JLM</div>	<div>Checked</div> <div>JM</div>	<div>Modified</div> <div>P&D</div>		<div>Project No.</div> <div>XXXXX</div>
		<div>Approved: Chief Of Staff</div>			<div>Location</div> <div>CAVHS LITTLE ROCK, AR</div>	<div>DRAWING NO.</div> <div>PL-3R</div>	<div>Dwg</div> <div>3</div> <div>Of</div> <div>6</div>		